NJDEP TERM CONTRACT -SUBSURFACE REMEDIATION & RECOVERY SERVICES X-28967

> COMBE FILL SOUTH LANDFILL CHESTER TOWNSHIP NEW JERSEY

BORING AND WELL DRILLING REPORT

Prepared by:

AccuTech Environmental Services, Inc.

Cass Street at Highway 35

Keyport, New Jersey 07735

Phone: (732)739-6444 Fax: (732)739-0451

Thomas H. Davis Senior Associate

NJDEP Cert No. 001074

July 28, 2000

511638

Combe Fill South Landfill Parker Road Chester Township, New Jersey

Boring and Well Drilling Report


Table of Contents

| 1.0 | AREA WIDE SITE PLAN |
|-----|-------------------------------|
| 2.0 | BORING AND WELL DRILLING LOGS |
| 3.0 | NOTES AND OBSERVATIONS |
| 4.0 | WELL PERMITS AND RECORDS |

WELL CERTIFICATION FORM-B

5.0

1.0 AREA WIDE SITE PLAN





| DRAWING TITLE FIGURE 2 - MONITORING WE | LL LOCATIONS |
|--|-----------------|
| DRAWING No. 4026/FIG2.DWG | |
| DATE: 9/25/00 | SCALE: 1" - 50" |
| DRAWN BY: SJG | |
| CHECKED DV. DAR | |

lelephone: Toll Free:

(908) 722-4266 (800) 242-6648 (732) 356-1009

FAX: http://www.summitdrilling.com email: info@summitdrilling.com

WELL LCG

ILL: RWT

ET WELL:

DATE ORTHLED: 04 07/0000 COORD #1: 25/10.732

PERMIT #1: 05-56113

CCCNTY: Morris

COORD #2:

DEVELOPMENT TIME: 1/2 Hour

PERMIT #2:

MSTREET:

ITE: Combe Fill Sc. Landfill Super, 96 Parker Road, , Thester, NJ ANER: NOTEF- Combe Fill South L. 401 East State Street, , Trenton, NJ 18628

SCREEN TYPE 1: Wire Wrap

USE: Recovery

MNER CASING: Steel/S St

CUTER CASING: Steel DIAMETER: 9"

SCREEN TYPE I:

DRILLING METHOD: Mud/Air Rotary SAMPLING METHOD:

LENGTH:

DIAMETER: LENGTH 1:

HOLE DIA: 12", 12"

IAMETER: 5"/5" ENGTH: 601/5" ENGTH:

GAL PER MIN: 20

LENGTH 2:

TOTAL DEPTH: 115

EAVEL PK S2: Morie #2 STAT H20 LVL: 40

.023 SLOT SIZE:

CASING SEAL: Fortland

50'

RILLER. Carmine DeCorso DEVELOPMENT METHOD: Pump URFACE COMPLETION: M

115'

BLOWS PER 6"

65'

OPEN HOLE:

FRCM - TC


DEPTH BELCW ON SAMPLER SURFACE

-EMARKS / SULLS ILENVIFICATION

1. 401 White-grey clay trace m/f sand & gravel.

.1'- 65' Weathered gneise.

45'- 115' Gneise.



3.0 NOTES AND OBSERVATIONS

All work was completed as per the NJDEP's engagement specification. NJDEP Geologist Gregory Giles logged the boring and was responsible for decision making regarding well construction. At Mr. Giles direction, the overburden well casing was set one (1) foot into competent bedrock, at a dept of 65°. No out of scope work was conducted.

4.0 WELL PERMITS WR-133M (10/96)

STATE OF NEW JERSEY

DEPARTMENT OF ENVIRONMENTAL PROTECTION TRENTON, NJ

Mail to-

COPIES:

MONITORING WELL PERMIT

Permit No. <u>2556/13</u>

1)DEÞ Bureau Water Allocation N 426

VALID ONLY AFTER APPROVAL BY TH

| HE D.E.P. | COORD #: | 25 1 | // ' | 729 |
|-----------|----------|---------|----------|-----|
| | COURD #. | V 12 17 | <u> </u> | 110 |

| rr NJ 08625-0426 | COORD #: 03.//./32 |
|--|--|
| Owner NJDEP - Combre File So. LF | Driller Summit Drilling Co., Inc. Central Jersey Industrial Park |
| Address 401 EAST STATE ST. | Address — Chimney Rock Road, Building 9W |
| TRENION NJ 08625 | Bound Brook, NJ 08805 |
| Name of Facility COMBE FILL SOUTH | Diameter of Well(s) 6 Inches Depth of Well(s) 120 Feet |
| 9/ DANKER ROAD | # of Wells / Will pumping equipment |
| 71561000 | Applied for (max. 10) be installed? YES NO |
| ['HISTER TWP | Type of Well (see reverse) RECOJE ~ 1 If Yes, give pump capacity S cumulative GPM |
| LOCATION | OF WELL(S) |
| Lot # Block # Municipality County Monnis | Draw sketch of well(s) nearest roads, buildings, etc. with marked distances in feet. Each well MUST be labeled with a name and/or number on the sketch. |
| State Atlas Map No | the state of the s |
| 40 ° 46' | 1200 |
| | |
| | |
| | |
| | 1,400 |
| | 1900 |
| } | |
| ` \ | |
| | |
| | ¥ NA |
| | I NI |
| 40 . 44 | BLDY T |
| FOR MONITORING WELLS. RECOVERY WELLS, OR PIEZOMETERS, THE FOLLOWING THE APPLICANT, PLEASE INDICATE WHY THE WELLS ARE BEING INSTALLED: | MUST BE COMPLETED BY This Space for Approval Stamp |
| □ Spill Site | |
| ☐ ISRA Site | |
| CERCLA (Superfund) Site | WELL PERMIT APPROVED |
| CRA Site | CASE I.D. Number N.J.D.E.P. |
| ☐ Underground Storage Tank Site | |
| Operational Ground Water Permit Site | MAR 2 9 2000 |
| Pretreatment and Residuals Site | |
| Water and Hazardous Waste Enforcement Case | Bulletin OF WASSER ALL CO. |
| Water Supply Aquifer Test Observation Well | BUREAU OF WATER ALLOCATION |
| Other (explain) | |
| FOR Issuance of this permit is subject to the conditions attached. (see next page | ge) The well(s) may not be completed with more than 25 feet of total screen |
| FOR Susuance of this permit is subject to the conditions attached. (see next part D.E.P. Sor monitoring purposes only | or uncased borehole. |
| USE D | the state of the s |
| S ERSE SIDE FOR IMPORTANT PROVISIONS AND REGULATIONS PERTAINING TO THIS PEF | MiT. |
| In pliance with N.J.S.A. 58:4A-14, application is made for a permit to di | rill a well as described above. |
| Date 3-27-00 Signature of Drille | When Banhau Registration No. 113751 |
| 2007 | Thomas Handy (ms) 1 |

| New 1/98 \$ | Jersey Department of E Bureau of Wate MONITORING W | r Allocati | on ECORD | | | |
|--|--|-------------|-----------------|-------------|--|--|
| o) a IDENTIFICATION - Owner | NJDEP-CHRE HILL | SO LF | Atlas Shee | | es <u> </u> | |
| Address 401 EAST | RIATE OF | | | | | · · · · · · · · · · · · · · · · · · · |
| City TRENTON | State | * | NJ . | ; | Zip Code : | *. \ <u>\</u> |
| | | 3 | | _ | | |
| VELL LOCATION - If not the same as ow | ner please give address. | Owners | Well No | <u> KW</u> | <u> </u> | · |
| Countynorris | Municipality CHE | STER IN | P. Lot | No1 | FINCK M | 0 |
| Address 96 PARKER RD | | <u></u> | | DATE WELL | _STARTED | 1 . 1 |
| TYPE OF WELL (as per Well Permit Cate | gorios) REGOVER | Υ | DAT | E WELL CO | OMPLETED | |
| Regulatory Program Requiring Well | gones) | • | | | <u>:</u> | |
| Regulatory Program frequiring Wen | | | 0236 1.1 | J.11 | | |
| CONSULTING FIRM/FIELD SUPERVISO | R (if applicable) | etecl | ` ;; | | Tele. # | ÷ |
| WELL CONSTRUCTION | Note: Measure all depths | Depth to | Depth to | Diameter | Material | Wgt./Rating |
| Total depth drilledft. | from land surface | Top (ft.) | Bottom (ft.) | (inches) | | (lbs/sch no.) |
| Well finished toft. | Single/Inner Casing | 0 | 60 65 | ر | Heel The | 1916 51.4 |
| Sorehole diameter: | Middle Casing | | | | 3.3 | |
| Topin. | (for triple cased wells only) | | | | 1 | |
| Bottomin. | Outer Casing | i, | _ | - 6 | | |
| Well was finished: above grade | (largest diameter) | 0 | کھا | 811 | Steel | 19165 |
| ffush mounted | Open Hole or Screen (No. Used, 020) | 5. | 115 | 9 | WITE | 5,440 |
| If finished above grade, casing height (stick up) above land surfaceft. | Blank Casings (No. Used | 3 | | | | 1.13 1.13 1.13 1.13 1.13 1.13 1.13 1.13 |
| W rel protective casing installed? | Tail Piece | -\$ | | | | |
| Static water level after drilling 40 ft. Water level was measured using 1000 | Gravel Pack | 45 | 115 | | Mores a | |
| Well was developed for hours | Grout | Ö | 65 | • | Neat Cement Bentonite | ILLY lbs. |
| atgpm | g G | routing M | ethod1 | Venie | | • |
| Method of development Punc | <u>) </u> | diling Me | thodmu | d-Air | Potory | <u> </u> |
| Was permanent pumping equipment installed | ? Tyes Tho | | | | : 1 | · |
| | i Little Bill | | · | | GIC LOG | · · · · · · · · · · · · · · · · · · · |
| Pump capacity gpm | | Note e | | ere water v | as encountered in | consolidated |
| Pump type: | · | 3 | uoris. | | • | , |
| Drilling FluidType | of Rig Guc Parla | 1,3 | | | | |
| | 179 | | | | | |
| Health and Safety Plan submitted? Wes [|] No ₄ .; | | Se Ce | The | | |
| Level of Protection used on site (circle one) | None O C B A | | | | | |
| I certify that I have constructed the a | bove referenced well in | · . | | | : | ! |
| accordance with all well permit requi | | * | | | | 30 |
| State rules and regu | | | | | | |
| Drilling Company SUMMIT | ELL DRILLING GO IN | c - | | | <u> </u> | er ver |
| D. | | 1 2 | • | | The Secretary of the Se | 347 |
| Well Driller (Print) (AVALUE De | LOKU | . | | | | |
| 10 | | 1 3 | · | | | • • |
| s Signature (61) | JHACLO _ | - | | | ·. · | |
| The same of the sa | 5. | | | | | |
| Registration No. 1110 | Date 5 / 11 / 00 | ٠ | | | | ' - |
| • | · | | | | | |
| COPIES: White - DEI | Canary - Driller | Pink - | Owner | Goldenro | d - Health Dept. | |

MONITORING WELL CERTIFICATION - FORM B - LOCATION CERTIFICATION

| Name of Permittee: Name of Facility: Location: - NJPDES Number: NJ00 | NJDEP Combe Fill South Chester, New Jersey or ECRA Case Number: |
|--|---|
| LAND SURVEYOR'S CERTIFICATION | |
| Well Permit Number: This number must be permanently affixed to the well casing | |
| Longitude (to nearest tenth second): | West 74° 44' 16.7" |
| Latitude (to nearest tenth second): Elevation of Top of Inner Casing (cap off) | North 40° 46'21.3" |
| (one-hundredth of a foot): | 819.25 TOP STEEL CASE |
| Source of elevation datum (benchmark, etc.) and | Source: WELL PZ-21 ON SITE |
| elevation (if an alternate datum has been approved by the Department, identify here and give | Elevation: 828.10 |

Owners Well Number (as shown on application or plans):

RW-T

Elevations are to be determined by double run, three wire leveling methods using balanced sights, commencing from a well marked and described point. This beginning point shall either be derived from Federal or State benchmarks if not more than 1000 feet from the site or, if the Department has approved an alternate datum, based on an assumed datum of 100. Tolerances should meet third order standards, which are 0.05 ft x (mile)1/2.

For sections less than 0.1 miles, let miles = 0.1.

AUTHENTICATION

approximated elevation):

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this document and all attachments and that, based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information accluding the possibility of fine and imprisonment.

PROFESSIONAL LAND SURVEYOR'S SIGNATURE

STEVEN D. PARENT, N.J. LICENSE NO. 36269

ELEVATION DESIGNATION MM-14 TOP CASE | 816.29 HM-14 GROUND 819.25 RM-T TOP CASE RH-T GROUND PZ-21 TOP PVC P2-21 TOP CASE 828.29 PZ-21 GROUND PZ-22 TOP PVC 623.46 P2-22 TOP CASE 824.09 PZ-22 GROUND PE-23 TOP PVC PZ-23 TOP CASE 817.50 PZ-23 GROUND 817.16 PZ-24 TOP PVC PZ-24 TOP CASE 817.42 PZ-24 GROUND

PARKER ROAD

Chk. SDP

9.45.00 Steven D. Parent

⊕PZ-22

@P2-21

Christian M. Kastrud

⊕P2-24

DATE 9/15/00 Dr 0.JU

SCALE I" = 50"

BLDG 9-W, CHIMNEY ROCK ROAD BOUND BROOK, NEW JERSEY 08805 PHONE 732.764.0100 FAX 732.764.0990 MONITORING WELL LOCATION MAP
FOR:
ACCUTECH ENVIRONMENTAL SERVICES

1. VERTICAL DATUM NAVO 1988. 2. FIELD SURVEY PERFORMED ON JUNE 9, 2000.

SITE: COMBE FILL SOUTH PARKER ROAD CHESTER, NEW JERSEY